

CARRIER SELECTION AND FIXTURE ROUGHING-IN DIMENSIONS

TYPE OF FIXTURE	ROUGH-IN DIMENSIONS	CARRIER SERIES	CARRIER MODEL	FIXTURE MANUFACTURER	FIXTURE MODEL
-----------------	---------------------	----------------	---------------	----------------------	---------------

MANSFIELD OPTIONS	<u>OPTION</u>	<u>DEFINITION</u>	MANSFIELD
<p><u>OPTIONS THAT AFFECT CARRIER SELECTION ARE IN BOLD TYPE</u></p>			

00-01-05	LAVATORY	A = 33-3/8 C = 17 F = 22 Δ = 35	17100-67	17100-67P	*	MANSFIELD	315 315-4 315-8 315-12
		See Introduction about changes to rough in dimensions.					20 X 27
00-10-11	URINAL	B = 33-15/16 C = 18-1/4 H = 14-15/16 J = 6-1/8 Δ = 24	17800 17810	17800-M1574 17810-M1574	* *	MANSFIELD	401
		See Introduction about changes to rough in dimensions.		These carriers are SP1 carriers with 4 additional holes drilled into the top plate to match Mansfield mounting bracket.			
13-10-04	URINAL	See Introduction about changes to rough in dimensions.	17560	17560-UR		MANSFIELD	410HE 410UHE CASCADE
03-07-31	URINAL	See Introduction about changes to rough in dimensions.	17800	17810-M1604		MANSFIELD	415 CASCADE II
98-09-18	URINAL	B = 36-1/8 C = 10-3/4 H = 18-3/4 E = 18-3/4 J = 4 Δ = 24	17810	17810-M1466		MANSFIELD	475 SUBURBAN
		See Introduction about changes to rough in dimensions.					

CARRIER SELECTION AND FIXTURE ROUGHING-IN DIMENSIONS

	TYPE OF FIXTURE	ROUGH-IN DIMENSIONS	CARRIER SERIES	CARRIER MODEL	FIXTURE MANUFACTURER	FIXTURE MODEL
97-08-04	LAVATORY	See Introduction about changes to rough in dimensions.	17550	17550	MANSFIELD	1613 SPRUCE COVE 16 X 13
13-04-18	LAVATORY	See Introduction about changes to rough in dimensions.	17550	17550	MANSFIELD	1917C WILLOW RUN 19 X 17
00-07-28	LAVATORY	A = 28-3/8 C = 17-1/8 F = 14 Δ = 31	17100 17120	17100-202P-H 17120-202P-H	MANSFIELD	2008 21 X 19
99-10-25	LAVATORY	See Introduction about changes to rough in dimensions. A = 29-1/2 C = 17-1/2 for -202 C = 17-1/8 for M1202 F = 16 Δ = 31	17100 17120 17550	17100-202P 17120-202P 17550SPM1202	* * MANSFIELD	2018C WALNUT KNOLL 19 X 17
05-06-24	LAVATORY	A = 29-1/2 C = 17-1/2 for -202 C = 17-1/8 for M1202 F = 16 Δ = 31	17100 17100-BB 17120 17125 17550	17100-202P 17100-BB-202P * 17120-202P 17125-202-AF 17550SPM1202	* * *	MANSFIELD 2018HB GRAND ISLE 20 X 18
00-07-28	LAVATORY	A = 28-3/8 C = 17-1/8 F = 14 Δ = 31	17100 17120	17100-202P-H 17120-202P-H	MANSFIELD	2018HB-NS 22 X 19
11-06-22	LAVATORY	See Introduction about changes to rough in dimensions.	17100	17100-202P	MANSFIELD	2038 2040

CARRIER SELECTION AND FIXTURE ROUGHING-IN DIMENSIONS

TYPE OF FIXTURE	ROUGH-IN DIMENSIONS	CARRIER SERIES	CARRIER MODEL	FIXTURE MANUFACTURER	FIXTURE MODEL
14-11-24 SINK	See Introduction about changes to rough in dimensions.	17730	17730	MANSFIELD	3072